### 2 - BUILDING REPAIRS AND REPLACEMENTS



Replace Exterior Brick Veneer & Windows, NHS Buildings D & E

> Temporary repairs to brick veneer in 2013 (typical of numerous locations)





#### 2 - BUILDING REPAIRS AND REPLACEMENTS







Renovate Restrooms, 11 Sites

- (top, left to right): Existing Sullivan MS restroom; existing NHS restroom
- ➤ (bottom, left to right): Rawlinson Road MS restored restroom; renovations to Phoenix Academy restrooms; renovated restroom at Sullivan MS.






Replace HVAC System, Applied Technology Center (Buildings B & C)

> Existing deteriorated boiler plant, ATC

#### 2 – BUILDING REPAIRS AND REPLACEMENTS

> Existing deteriorated rooftop heating and cooling units, ATC (over 20 years old)





Roofing Replacements, 15 Sites

- (left): Roof leak damage, Flexible Learning Center
- > (right): Existing deteriorated roof, showing failure by buckling (typical)

### 2 – BUILDING REPAIRS AND REPLACEMENTS







#### **Upgrade Classroom Furnishings**


> Various new classroom systems: (top) VS America; (middle) Steelcase; (bottom) Smith System

#### 2 – BUILDING REPAIRS AND REPLACEMENTS
















### Replace / Upgrade Custodial Equipment

- (top, left to right): old vacuum, mop buckets; old buffers
- (middle, left): new custodial carts;
- (middle, right): ByoPlanet CS 900 electrostatic room disinfection machine
- ➤ (bottom): new "green" floor refinishing machines